

**MACHINES**

[Vertical Machining Centers](#)

[Horizontal Machining Centers](#)

[Machine Selector Guide](#)

[HMC400](#)

[HMC500](#)

[HM500S/40](#)

[HM500S/50](#)

[HM600](#)

[HM6300S](#)

[HM800S](#)

[HM1000S](#)

[HM1250S](#)

[HM1600](#)

[MCH600](#)

[MCH8000](#)

[MCH10000](#)

[5-Axis Machines](#)

[Blade Centers](#)

[Die Mold Machines](#)

[FMS System](#)

[Mass Production](#)

[Aerospace](#)

## Machines

### HM600



[Click to enlarge](#)



New concepts in high-speed machining offer drastic improvements in speed, rigidity and durability over competing machines. Our HM series offers the fastest and most powerful machines in their class, while providing easy access, maintenance and operation

#### Main Specification and Downloads

<b>X Axis Travel:</b>	780(30.71")
<b>Y Axis Travel:</b>	750(29.53")
<b>Z Axis Travel:</b>	800(31.50")
<b>Rapid Tranverse Rate:</b>	75m/min (2,953ipm)
<b>Spindle Speeds:</b>	35 to 12,000
<b>Spindle Motor:</b>	40/33HP
<b>Spindle Taper:</b>	No.50
<b>Magazine Capacity:</b>	60 (OP: 40, 80, 116, 176, 300)
<b>Table Size:</b>	630 (24.80")

